




## **High-Profile Site**

- Boathouse Row National Historic Landmark
  - Olympic rowing training facility
  - Last successfully dredged in 1999
  - Mud and land in front of boathouses



#### **Environmental Windows**



Fish spawning – Prior to June 30




Red-bellied turtle hibernation - Oct. 15 and beyond

#### **Mobilization Plan**

Construction site to CDF:

7 miles

16 bridge crossings



## **Customized Dredge**

Compact

36 feet long

22 tons

Front stabilizers

Rear spuds

Able to work in shallow water and narrow channels



# **Specialized Equipment**

Submersible dredge pump
Barge-mounted excavator
2 spud barges



## **Challenging Dredging Conditions**

Hard clay, silt and mud Sand mixed with coal Anthracite coal lumps Debris (150 cubic yards)



#### Conclusion

**Boathouse Row restored** 



#### Let's Connect

www.michels.us











